



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

MARY ANN WRIGHT
Acting Division Director

Supervisor 10024

Inspection Report
Minerals Regulatory Program
Report Date: February 28, 2005

Mine Name: Michaud #1 - #4 Claims

Operator or Permittee Name:

Patrick A. Michaud

Permittee Mailing Address:

43663 Acacia Drive
Palm Desert, California 92260

Permit number: S/053/075

Inspection Date: February 3, 2005

Inspector(s): Doug Jensen

Other Participants: None

Permit Status: Inactive

Current Acreages:

Total Permitted (Bonded): <5 acres

Total Disturbed: <5 acres

Weather: warm

Inspection Start Time: 7:00 AM

Inspection End Time: 7:30 AM

Site location/Area Inspected (i.e. Pit #):

Quarry

Surface Ownership: BLM

Mineral Ownership: BLM

Mineral Mined: Sandstone

Type of Mine: Quarry

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Inspection Date: February 3, 2005 ; Report Date: February 28, 2005

Page 2 of 2

S/053/075

Purpose of Inspection:

While in the area, stopped to check the site.

Inspection Summary:

The site appears to have had very little activity since my last visit. Some traffic appears to have entered into the disturbed area, but there does not appear to have been any quarrying activities.

The site is located in a small ephemeral drainage but there does not appear that any water has flowed through the area.

The site is stable and there has been little impacts to the surrounding areas because of this disturbance.


Directions to the site:

The site is located north of the Hurricane exit and can be seen from the I-15 corridor.

GPS data:

None gathered

Inspector's Signature



Date: February 28, 2005

DJ:jb

Enclosures: photos

cc: Patrick Michaud, Operator

Rody Cox, BLM, St. George FO

O:\M053-Washington\S0530075-Michaud1-4\inspections\insp-02032005.doc